



# Mani Bhadra BV - Phoenix Import

De Vesting 14  
7722 GA Dalfsen  
The Netherlands

Tel.: +31 (0)38 4235510  
E-mail: [info@phoeniximport.nl](mailto:info@phoeniximport.nl)  
Website: [www.phoeniximport.com](http://www.phoeniximport.com)

Chamber of Commerce  
Zwolle N° 05050712  
VAT: NL821251715B01

## GPSR information

### Product information

**Name:** Ispalla incienso Buenos Días

**Article number:** 19848

**EAN:** 8718657469492

**Manufacturer:** Mani Bhadra BV - Phoenix Import

**Manufacturer's address:** De Vesting 14, 7722GA Dalfsen, The Netherlands

**Manufacturer's email address:** [info@phoeniximport.nl](mailto:info@phoeniximport.nl)

**Country of origin:** Peru

### Specifications

**Size cm:** 22.5

**Weight g:** 12 x 13

**Prijs per:** 12 pakketes

**Total weight g:** 330

**Packaging:** Caja de cartón

**Burn time (min):** Ø 50

**Land van herkomst:** Perú

### Contact Information of the Responsible Market Participant in the EU

**Name:** Mani Bhadra BV - Phoenix Import

**Address:** De Vesting 14, 7722GA Dalfsen, The Netherlands

**Phone number:** +31 384 235 510

**Email address:** [info@phoeniximport.nl](mailto:info@phoeniximport.nl)

**Website:** [www.phoeniximport.com](http://www.phoeniximport.com)

### Hazards and Precautions

#### Danger or Warning:

- Warning

#### GHS Pictograms



#### H-statements

- H315 - Veroorzaakt huidirritatie.
- H317 - Kan een allergische huidreactie veroorzaken.
- H412 - Schadelijk voor in het water levende organismen, met langdurige gevolgen.

#### P-statements:

- P101 - Bij het inwinnen van medisch advies, de verpakking of het etiket ter beschikking houden.
- P102 - Buiten het bereik van kinderen houden.
- P261 - Inademing van stof/rook/gas/nevel/damp/spuitnevel vermijden.
- P264 - Lavarse ... concienzudamente tras la manipulación.
- P280 - Beschermende handschoenen/beschermende kleding/oogbescherming/gelaatsbescherming dragen.
- P501 - Inhoud/verpakking afvoeren naar ...

**This technical dossier is still under development and is regularly updated and supplemented with new information. The information in this document is intended solely to support product safety and transparency. While we have made every effort to ensure the accuracy and completeness of the information provided, we cannot guarantee that the dossier is free from errors or omissions. This document is prepared to support product safety and transparency but does not replace the assessment or approval by competent authorities. Use of the information is at your own risk. For questions or further clarification, please contact our customer service.**